

GROUP 16 – ENGINE ELECTRICAL

BULLETIN No.	SUBJECT	MODEL
16/2003/001	Surface discharge spark plugs	6G7



MITSUBISHI

SERVICE BULLETIN

GROUP: 16 – Engine Electrical

DATE: November 2003

NO. 16/2003/001

MODEL: 6G7 – Engine

SUBJECT: Surface discharge spark plugs

COUNTRIES:


Australia

R.I.WYATT
MANAGER - AFTERSALES
TECHNICAL SUPPORT

Bulletin Consists of 1 Pages

The purpose of this bulletin is to advise of the change of spark plug fitted to the 6G7 engine of the light commercial range of vehicles. With the introduction of the 04 Model Year, the Platinum spark plug is no longer fitted to the V6 engine. It has been replaced by a 3-ground electrode, semi surface discharge type plug. While this plug is not platinum, it is a long life plug and the service interval for replacement is the same as platinum plugs eg:100,000 Kms. As this plug is fitted to all 6 cylinders, there is no requirement during regular scheduled servicing for any spark plugs to be changed until the vehicle has attained 100,000 Km.

AFFECTED 04 M/Y VEHICLES	AFFECTED ENGINES	SPARK PLUG
PA Challenger	6G7 V6 3.0L	BKR6ETUB
NP Pajero	6G7 V6 3.5L 6G7 V6 3.8L	BKR6ETUB BKR6ETUB
MK Triton	6G7 V6 3.0L	BKR6ETUB



NOTE: Service and warranty book is currently being revised to reflect the changes to servicing schedules.

NOTE: THIS BULLETIN SHOULD BE FORWARDED DIRECT TO THE SERVICE MANAGER FOR ACTION/DISTRIBUTION.

Copyright © Mitsubishi Motors Australia Limited.
Reproduction in whole or part prohibited without written approval.